

**TESLA MOTORS HK LIMITED**

G/F,Unit A&B, HK Industrial Building,  
444-452 Des Voeux Road, Sai Wan,  
Hong Kong Island 444-452 Des  
Voeux Road West

Hong Kong,,HK 852

Ph.: + 852 3974 0278

**Invoice**

**SERVICE DEPARTMENT HOURS**  
Mon-Fri 9:00 a.m. to 6:00 p.m.

Invoice date	Invoice number
May-2023	
Due Date	
Date/Time Received	Date/Time Promised
Odometer In	Odometer Out
71860 Kilometers	Kilometers
Ready Date	SV Number
Service Advisor	

**Paid**

Bill To

Mobile Phone	Additional Phone		Vehicle Identification Number
Year	Model	License Plate Number	Colour
2020	MODEL 3		Pearl White Multi-Coat

Job Number	Description Of Work	Amount (HKD)																																																								
1	<p><b>Concern:</b> Customer states: Rattle or Squeak - Upper arm control noise</p> <p>Replaced: Control Arm - Upper - Front - Pair Links - Lateral - Lower - Front - LH/RH Links - Compliance - Lower - Front - RH/LH Knuckle - Suspension - Rear - Pair</p> <p><b>**REMARKS**</b> Customer will carry out the 4 wheel alignment by himself in outside garage due to third party suspension parts</p> <table><tr><td><b>Correction: General Diagnosis</b></td><td><b>Price</b></td><td><b>Adjustment</b></td><td><b>Subtotal</b></td></tr><tr><td></td><td>750.00</td><td>0.00</td><td>750.00</td></tr><tr><td><b>Correction: Control Arm - Upper - Front - Pair(Remove and Replace)</b></td><td><b>Price</b></td><td><b>Adjustment</b></td><td><b>Subtotal</b></td></tr><tr><td></td><td>0.00</td><td>0.00</td><td>0.00</td></tr><tr><td colspan="4"><b>Parts Replaced or Added</b></td></tr><tr><td><b>Part</b></td><td><b>Quantity</b></td><td><b>Unit Price</b></td><td><b>Price</b></td><td><b>Adjustment</b></td><td><b>Subtotal</b></td></tr><tr><td>NUT,HF,M12-1.75, [10],ZNNI,PTP.(1111543-00-A)</td><td>2.00</td><td>4.30</td><td>8.60</td><td>0.00</td><td>8.60</td></tr><tr><td>NUT,HF,M10-1.5, [10],ZNNI,PTP.(1111145-00-A)</td><td>2.00</td><td>3.91</td><td>7.82</td><td>0.00</td><td>7.82</td></tr><tr><td>FR UPR CTRL ARM ASSY, RH(1044326-00-J)</td><td>1.00</td><td>680.00</td><td>680.00</td><td>0.00</td><td>680.00</td></tr><tr><td>FR UPR CTRL ARM ASSY, LEFT HAND(1044321-00-J)</td><td>1.00</td><td>680.00</td><td>680.00</td><td>0.00</td><td>680.00</td></tr><tr><td colspan="4"><b>Parts Subtotal</b></td><td><b>1,376.42</b></td><td></td></tr></table>	<b>Correction: General Diagnosis</b>	<b>Price</b>	<b>Adjustment</b>	<b>Subtotal</b>		750.00	0.00	750.00	<b>Correction: Control Arm - Upper - Front - Pair(Remove and Replace)</b>	<b>Price</b>	<b>Adjustment</b>	<b>Subtotal</b>		0.00	0.00	0.00	<b>Parts Replaced or Added</b>				<b>Part</b>	<b>Quantity</b>	<b>Unit Price</b>	<b>Price</b>	<b>Adjustment</b>	<b>Subtotal</b>	NUT,HF,M12-1.75, [10],ZNNI,PTP.(1111543-00-A)	2.00	4.30	8.60	0.00	8.60	NUT,HF,M10-1.5, [10],ZNNI,PTP.(1111145-00-A)	2.00	3.91	7.82	0.00	7.82	FR UPR CTRL ARM ASSY, RH(1044326-00-J)	1.00	680.00	680.00	0.00	680.00	FR UPR CTRL ARM ASSY, LEFT HAND(1044321-00-J)	1.00	680.00	680.00	0.00	680.00	<b>Parts Subtotal</b>				<b>1,376.42</b>		15,878.42
<b>Correction: General Diagnosis</b>	<b>Price</b>	<b>Adjustment</b>	<b>Subtotal</b>																																																							
	750.00	0.00	750.00																																																							
<b>Correction: Control Arm - Upper - Front - Pair(Remove and Replace)</b>	<b>Price</b>	<b>Adjustment</b>	<b>Subtotal</b>																																																							
	0.00	0.00	0.00																																																							
<b>Parts Replaced or Added</b>																																																										
<b>Part</b>	<b>Quantity</b>	<b>Unit Price</b>	<b>Price</b>	<b>Adjustment</b>	<b>Subtotal</b>																																																					
NUT,HF,M12-1.75, [10],ZNNI,PTP.(1111543-00-A)	2.00	4.30	8.60	0.00	8.60																																																					
NUT,HF,M10-1.5, [10],ZNNI,PTP.(1111145-00-A)	2.00	3.91	7.82	0.00	7.82																																																					
FR UPR CTRL ARM ASSY, RH(1044326-00-J)	1.00	680.00	680.00	0.00	680.00																																																					
FR UPR CTRL ARM ASSY, LEFT HAND(1044321-00-J)	1.00	680.00	680.00	0.00	680.00																																																					
<b>Parts Subtotal</b>				<b>1,376.42</b>																																																						

<b>Correction: Links - Lateral - Lower - Front - LH/RH (Remove &amp; Replace)</b>			<b>Price</b>	<b>Adjustment</b>	<b>Subtotal</b>
			720.00	0.00	720.00
<b>Parts Replaced or Added</b>					
<b>Part</b>	<b>Quantity</b>	<b>Unit Price</b>	<b>Price</b>	<b>Adjustment</b>	<b>Subtotal</b>
NUT&WSHR[SW],M14X1.5, [10],ZNFL,PTP.(1109263-00-B)	2.00	22.00	44.00	0.00	44.00
LOWER LATERAL LINK - FRONT(1044341-00-D)	2.00	1,350.00	2,700.00	0.00	2,700.00
<b>Parts Subtotal 2,744.00</b>					
<b>Correction: Links - Compliance - Lower - Front - RH/LH (Remove and Replace)</b>			<b>Price</b>	<b>Adjustment</b>	<b>Subtotal</b>
			810.00	0.00	810.00
<b>Parts Replaced or Added</b>					
<b>Part</b>	<b>Quantity</b>	<b>Unit Price</b>	<b>Price</b>	<b>Adjustment</b>	<b>Subtotal</b>
NUT&WSHR[SW],M14X1.5, [10],ZNFL,PTP.(1109263-00-B)	2.00	22.00	44.00	0.00	44.00
FRONT LOWER COMPLIANCE LINK ASSEMBLY, RIGHT HAND(1044359-00-A)	1.00	1,170.00	1,170.00	0.00	1,170.00
FRONT LOWER COMPLIANCE LINK ASSEMBLY, LEFT HAND(1044354-00-A)	1.00	1,170.00	1,170.00	0.00	1,170.00
<b>Parts Subtotal 2,384.00</b>					
<b>Correction: Knuckle - Suspension - Rear - LH (Remove &amp; Replace)</b>			<b>Price</b>	<b>Adjustment</b>	<b>Subtotal</b>
			1,350.00	0.00	1,350.00
<b>Parts Replaced or Added</b>					
<b>Part</b>	<b>Quantity</b>	<b>Unit Price</b>	<b>Price</b>	<b>Adjustment</b>	<b>Subtotal</b>
NUT&WSHR[SW],M24, STL[8],ZNFL,SERR.(1115558-00-A)	1.00	47.00	47.00	0.00	47.00
RR KNUCKLE ASSY, LEFT HAND(1044411-00-G)	1.00	2,150.00	2,150.00	0.00	2,150.00
<b>Parts Subtotal 2,197.00</b>					
<b>Correction: Knuckle - Suspension - Rear - RH (Remove &amp; Replace)</b>			<b>Price</b>	<b>Adjustment</b>	<b>Subtotal</b>
			1,350.00	0.00	1,350.00
<b>Parts Replaced or Added</b>					
<b>Part</b>	<b>Quantity</b>	<b>Unit Price</b>	<b>Price</b>	<b>Adjustment</b>	<b>Subtotal</b>
NUT&WSHR[SW],M24, STL[8],ZNFL,SERR.(1115558-00-A)	1.00	47.00	47.00	0.00	47.00
RR KNUCKLE ASSY, RH(1044416-00-G)	1.00	2,150.00	2,150.00	0.00	2,150.00

	<div>Parts Subtotal 2,197.00</div> <div>Pay Type: Customer Pay</div> <div>Total Parts Amount 10,898.42</div> <div>Total Labor Amount 4,980.00</div>				
2	<div>Concern: 2nd annual service</div> <div>2nd Annual Service</div> <div>Replaced front wiper blades.</div> <div>Replaced cabin air filter.</div> <div>Performed thermal system test</div> <div>Checked cooling system / Topped up coolant</div> <div>Front brake pads 7 mm,</div> <div>Rear brake pads 7 mm,</div> <div>Refill washer fluid</div> <div>Flushed brake fluid system</div> <div>Lubricated all door latches</div> <div>Inspected seat belts</div> <div>Checked / Re-torqued Front Ground Nuts</div> <div>Adjusted all tire pressure to 42 psi,</div> <div>All wheel nuts torqued, Suspension - Front and Rear- Checked Torque</div> <div>Performed latest firmware update / Map update</div> <div>Tire Thread Depth</div> <div>FL 5 mm</div> <div>FR 5 mm</div> <div>RL 3 mm</div> <div>RR 3 mm</div> <div><div>Correction: Filter - Cabin (Remove &amp; Replace)</div><div>Price</div><div>Adjustment</div><div>Subtotal</div><div>150.00</div><div>0.00</div><div>150.00</div></div> <div>Parts Replaced or Added</div> <div><div>Part</div><div>Quantity</div><div>Unit Price</div><div>Price</div><div>Adjustment</div><div>Subtotal</div><div>HVAC - COMBINATION</div><div>2.00</div><div>139.00</div><div>278.00</div><div>0.00</div><div>278.00</div><div>FILTER(1107681-00-C)</div><div><div>Parts Subtotal 278.00</div></div></div> <div><div>Correction: Tire Rotation</div><div>Price</div><div>Adjustment</div><div>Subtotal</div><div>300.00</div><div>0.00</div><div>300.00</div></div> <div><div>Correction: Perform General Inspection</div><div>Price</div><div>Adjustment</div><div>Subtotal</div><div>975.00</div><div>0.00</div><div>975.00</div></div> <div><div>Correction: Wiper Blades (Remove &amp; Replace)</div><div>Price</div><div>Adjustment</div><div>Subtotal</div><div>90.00</div><div>0.00</div><div>90.00</div></div> <div>Parts Replaced or Added</div> <div><div>Part</div><div>Quantity</div><div>Unit Price</div><div>Price</div><div>Adjustment</div><div>Subtotal</div><div>M3 WIPER BLADE PS</div><div>1.00</div><div>179.00</div><div>179.00</div><div>0.00</div><div>179.00</div><div>RIGHT HAND</div><div>DRIVE(1096470-00-A)</div><div>M3 WIPER BLADE DR</div><div>1.00</div><div>179.00</div><div>179.00</div><div>0.00</div><div>179.00</div><div>RIGHT HAND</div><div>DRIVE(1096469-00-A)</div></div>				3,979.00



Notes:

Discount	0.00
<b>Subtotal (HKD)</b>	19,857.42
Tax	0.00
<b>Total Amount (HKD)</b>	19,857.42
<b>Total Paid (HKD)</b>	19,857.42
<b>Payment Due (HKD)</b>	0.00

You agree that: Tesla is not responsible for any personal items left in your vehicle; Tesla, its affiliates and their respective employees may access and operate your vehicle or transport your vehicle to another Tesla service location for the sole purpose of repairs, testing and/or inspection of repairs; Tesla, its affiliates and their respective employees may access, download and use the information stored on your vehicles data recorder to service and diagnose issues with your vehicle, and Tesla may store and aggregate such data for its own purposes; an express mechanics lien is hereby acknowledged on your vehicle to secure the amount of repairs and storage; the owners insurance provides exclusive coverage for the vehicle while it is in Teslas possession; and you may be charged storage fees from the fourth day after you are notified that repairs on your vehicle are complete. Tesla disclaims all express or implied warranties with respect to any repairs or products used in repairs, except as may be set forth in your Tesla-issued New Vehicle Limited Warranty or other extended service agreement. Tesla is not responsible for repairs not performed by, or components not installed by, Tesla. You authorize the repair work, including parts, materials and labor, on your vehicle to be done as set forth in this service agreement document. Goods presented for repair may be replaced by refurbished goods of the same type rather than being repaired. Refurbished parts may be used to repair the goods.

Any parts (including tires/wheels) removed or replaced by Tesla during vehicle service will become the property of Tesla. However, at the time you authorize repairs, you may request to receive (subject to any applicable core charge, which you agree to pay) or inspect replaced parts (excluding inflatable restraint system components), except body shop repair parts and parts required to be returned to the manufacturer or a third party under a warranty, trade-in or exchange agreement, which will only be presented to you for examination and not returned.

Signature:

Date:

---

The warranty period will be extended for the number of whole days that the product has been out of the buyer's hands for warranty repairs. If a defect exists within the warranty period, the warranty will not expire until the defect has been fixed. The warranty period will also be extended if the warranty repairs have not been performed due to delays caused by circumstances beyond the control of the buyer, or if the warranty repairs did not remedy the defect and the buyer notifies the manufacturer or seller of the failure of the repairs within 60 days after they were completed. If, after a reasonable number of attempts, the defect has not been fixed, the buyer may return this product for a replacement or a refund subject, in either case, to deduction of a reasonable charge for usage. This time extension does not affect the protections or remedies the buyer has under other laws.