

**TESLA MOTORS HK LIMITED**

西環 香港工業大廈 西環德輔道西
444-452號地下G/F,Unit A&B, HK
Industrial Building, 444-452 Des
Voeux Road, Sai Wan

Hong Kong,HONG KONG
ISLAND,HK 852

Ph.: + 852 3974 0278

Invoice

SERVICE DEPARTMENT HOURS
Mon-Fri 9:00 a.m. to 6:00 p.m.

Invoice date	Invoice number
-May-2025	
Due Date	
Date/Time Received	Date/Time Promised
Odometer In	Odometer Out
144135 Kilometers	144136 Kilometers
Ready Date	SV Number
Service Advisor	

Paid

Bill To

Mobile Phone	Additional Phone	Vehicle Identification Number	
Year	Model	License Plate Number	Colour
2020	MODEL 3		Pearl White Multi-Coat

Job Number	Description Of Work					Amount (HKD)
1	Concern: Customer states: Maintenance - Cabin Air Filter Replacement					1,766.00
	Repair Notes: -Annual service -Checked firmware version: Up to date -Suspension - Front - Check Torque -Suspension - Rear - Check Torque -Replaced Cabin air filter -Replaced wiper blade -Wheel lug nuts torqued. -Topped off washer fluid. -Verified wiper and washer jet operation: Good, no issue. -Adjusted tire pressure to: 42 PSI front, 42 PSI rear. -Measured tire tread depth at: (Outer) (Center) (Inner) FR: 7mm 7mm 7mm FL: 7mm 7mm 7mm RR: 7mm 7mm 7mm RL: 7mm 7 mm 7mm Brake pad thickness:mm FL:5 FR:5 RR: 5 RL:5 Hand brake:5					
Correction: Filter - Cabin (Remove & Replace) - Remove and Replace		Labor Hours	Price	Adjustment	Subtotal	
		0.18	270.00	0.00	270.00	
Parts Replaced or Added						
Part	Quantity	Unit Price	Price	Adjustment	Subtotal	
HVAC - COMBINATION FILTER - APAC(1813371-00-B)	2.00	139.00	278.00	0.00	278.00	
Parts Subtotal 278.00						
Correction: Perform General Inspection		Labor Hours	Price	Adjustment	Subtotal	

		0.50	750.00	0.00	750.00																		
	Correction: Wiper Blades (Remove & Replace) - Remove and Replace	Labor Hours	Price	Adjustment	Subtotal																		
		0.06	90.00	0.00	90.00																		
	Parts Replaced or Added																						
	Part	Quantity	Unit Price	Price	Adjustment																		
	WIPER BLADE PS RIGHT HAND DRIVE(1096470-00-A)	1.00	179.00	179.00	0.00																		
	WIPER BLADE DR RIGHT HAND DRIVE(1096469-00-A)	1.00	179.00	179.00	0.00																		
					Parts Subtotal 358.00																		
	Correction: No Labor Performed - Part Replaced	Labor Hours	Price	Adjustment	Subtotal																		
		0.00	0.00	0.00	0.00																		
	Parts Replaced or Added																						
	Part	Quantity	Unit Price	Price	Adjustment																		
	Wurth Concentrated Windshield Washer 0892333(1089984-05-A)	1.00	20.00	20.00	0.00																		
					Parts Subtotal 20.00																		
					Pay Type: Customer Pay																		
	Total Parts Amount	656.00																					
	Total Labor Amount	1,110.00																					
	Labor Hours	0.74																					
2	Concern: Customer states: Windshield - Cracked Repair Notes: Windshield (Reuse Humidity and Temperature Sensor) (Remove & Replace) - Remove and Replace Correction: Windshield (Reuse Humidity and Temperature Sensor) (Remove & Replace) - Remove and Replace Parts Replaced or Added <table> <tr> <td>Part</td><td>Quantity</td><td>Unit Price</td><td>Price</td><td>Adjustment</td><td>Subtotal</td></tr> <tr> <td>WSHLD ASSY RIGHT HAND DRIVE IR ACOUSTIC(1524888-S0-A)</td><td>1.00</td><td>4,369.07</td><td>4,369.07</td><td>0.00</td><td>4,369.07</td></tr> <tr> <td>SEALANT - BETASEAL EXPRESS - 400 MILILITER BOTTLE(1048645-00-A)</td><td>2.00</td><td>126.00</td><td>252.00</td><td>0.00</td><td>252.00</td></tr> </table>					Part	Quantity	Unit Price	Price	Adjustment	Subtotal	WSHLD ASSY RIGHT HAND DRIVE IR ACOUSTIC(1524888-S0-A)	1.00	4,369.07	4,369.07	0.00	4,369.07	SEALANT - BETASEAL EXPRESS - 400 MILILITER BOTTLE(1048645-00-A)	2.00	126.00	252.00	0.00	252.00
Part	Quantity	Unit Price	Price	Adjustment	Subtotal																		
WSHLD ASSY RIGHT HAND DRIVE IR ACOUSTIC(1524888-S0-A)	1.00	4,369.07	4,369.07	0.00	4,369.07																		
SEALANT - BETASEAL EXPRESS - 400 MILILITER BOTTLE(1048645-00-A)	2.00	126.00	252.00	0.00	252.00																		
		2.40	3,600.00	0.00	3,600.00																		
					Parts Subtotal 4,621.07																		

		Pay Type: Customer Pay
	Total Parts Amount	4,621.07
	Total Labor Amount	3,600.00
	Labor Hours	2.40

Service Center hourly rate: HKD 1500

All parts are new unless otherwise specified.

Notes:

Total Parts (HKD)	5,277.07
Total Labor (HKD)	4,710.00
Discount	0.00
Subtotal (HKD)	9,987.07
Tax	0.00
Total Amount (HKD)	9,987.07
Payment Due (HKD)	0.00
Total Paid (HKD)	9,987.07

You agree that: Tesla is not responsible for any personal items left in your vehicle; Tesla, its affiliates and their respective employees may access and operate your vehicle or transport your vehicle to another Tesla service location for the sole purpose of repairs, testing and/or inspection of repairs; Tesla, its affiliates and their respective employees may access, download and use the information stored on your vehicles data recorder to service and diagnose issues with your vehicle, and Tesla may store and aggregate such data for its own purposes; an express mechanics lien is hereby acknowledged on your vehicle to secure the amount of repairs and storage; the owners insurance provides exclusive coverage for the vehicle while it is in Teslas possession; and you may be charged storage fees from the second day after repairs to your Vehicle are complete. Tesla disclaims all express or implied warranties with respect to any repairs or products used in repairs, except as may be set forth in your Tesla-issued New Vehicle Limited Warranty or other extended service agreement. Tesla is not responsible for repairs not performed by, or components not installed by, Tesla. You authorize the repair work, including parts, materials and labor, on your vehicle to be done as set forth in this service agreement document. Goods presented for repair may be replaced by refurbished goods of the same type rather than being repaired. Refurbished parts may be used to repair the goods.

Any parts (including tires/wheels) removed or replaced by Tesla during vehicle service will become the property of Tesla. However, at the time you authorize repairs, you may request to receive (subject to any applicable core charge, which you agree to pay) or inspect replaced parts (excluding inflatable restraint system components), except body shop repair parts and parts required to be returned to the manufacturer or a third party under a warranty, trade-in or exchange agreement, which will only be presented to you for examination and not returned.

Signature:

Date:

The warranty period will be extended if the warranty repairs have not been performed due to delays caused by circumstances beyond the control of the buyer, or if the warranty repairs did not remedy the defect and the buyer notifies the manufacturer or seller of the failure of the repairs within 60 days after they were completed. If, after a reasonable number of attempts, the defect has not been fixed, the buyer may return this product for a replacement or a refund subject, in either case, to deduction of a reasonable charge for usage. This time extension does not affect the protections or remedies the buyer has under other laws.