



**TESLA MOTORS HK LIMITED**  
7 Ko Fai RoadG/F, Block B, Ko Fai  
Industrial Building  
Yau Tong.,HK 852  
Ph.: 39740298

## Invoice

**SERVICE DEPARTMENT HOURS**  
Mon-Fri 9:00 a.m. to 6:00 p.m.

Invoice date	Invoice number
-Sep-2021	
Date/Time Received	Date/Time Promised
Odometer In	Odometer Out
27915 Kilometers	27915 Kilometers
Ready Date	
Service Advisor	

**Paid**

Bill To	Mobile Phone	Additional Phone	Vehicle Identification Number
Year	Model	License Plate Number	Colour
2020	MODEL 3		Pearl White Multi-Coat

Job Number	Description Of Work					Amount (HKD)	
1	<b>Concern:</b> Windshield & top glass - customer states: Windshield glass has stone chip with crack & request to replace windshield glass.						
	Replaced windshield glass assembly.						
	<b>Correction: Windshield (Vehicles with 2nd Generation or Later Autopilot Hardware) (Remove &amp; Replace)</b>			<b>Price</b>	<b>Adjustment</b>		<b>Subtotal</b>
				2,767.50	0.00		2,767.50
	<b>Parts Replaced or Added</b>						
	<b>Part</b>	<b>Quantity</b>	<b>Unit Price</b>	<b>Price</b>	<b>Adjustment</b>		<b>Subtotal</b>
	WSHLD ASSY RHD IR ACOUSTIC(1478041-00-A)	1.00	4,110.00	4,110.00	0.00		4,110.00
	SEALANT, BETASEAL EXPRESS/EXPRESS + (1048645-00-A)	2.00	120.00	240.00	0.00		240.00
	<b>Parts Subtotal 4,350.00</b>						
	Pay Type: Customer Pay						
<b>Total Parts Amount 4,350.00</b>							
<b>Total Labor Amount 2,767.50</b>					<b>7,117.50</b>		

Service Center hourly rate: HKD 1350

All parts are new unless otherwise specified.

Notes:

Total Parts (HKD)	4,350.00
Total Labor (HKD)	2,767.50
Discount	0.00
<b>Subtotal (HKD)</b>	<b>7,117.50</b>
Tax	0.00
<b>Total Amount (HKD)</b>	<b>7,117.50</b>
<b>Total Paid (HKD)</b>	<b>7,117.50</b>
<b>Payment Due (HKD)</b>	<b>0.00</b>